

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2020

Submitted Date:

02/01/2020

Document Number:

696102082**FIELD INSPECTION FORM**Loc ID 306658 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290385	WELL	SI	01/01/2017	OW	123-25078	WELLS RANCH-USXAA 35-19	TA

**General Comment:**

This is a WELL / ABANDONED BATTERY inspection.  
 Well(s): 1: Temporarily Abandoned | TA.  
 Battery: Abandoned. ALL equipment has been removed.  
 Reclamation progressing.  
 Abandoned Battery SE corner GPS coordinates: 40.447330, -104.408390

Abandoned Centralized Battery formerly served 5 Location IDs (306658, 302638, 310088, 310089, 310130).  
 (Well(s): 5: Temporarily Abandoned | TA).

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	Motor oil			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	STORAGE OF SUPL			
Comment:	Unused Equipment / Supplies at wellsite. 7 drums motor oil. 2 drip trays. Refer to Rule 603.f. See photo #3.			
Corrective Action:	Remove 7 drums motor oil, 2 drip trays from Temporarily Abandoned   TA wellsite. Comply w/ Rule 603.f. See photo #3.			Date: 02/18/2020
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
<b>Equipment:</b>				
			corrective date	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			

Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 290385 Type: WELL API Number: 123-25078 Status: SI Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

**Comment:** Temporarily Abandoned | TA.  
 Battery Abandoned: All Equipment Removed.  
 COGCC records indicate last production: 11/2016.  
 SI/TA well per variance doc. #401474555. (NOBLE).  
 Yellow LTSI & Orange Facility Decommissioned tags for SI/TA status present at wellsite.  
 Locked-Out, Tagged Out | LOTO.

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On SAT 02/01/2020 at approximately 10:23 hrs. I, Bret Evins, conducted an on-site inspection at:            Operator Name: NOBLE ENERGY INC            Location Name: WELL RANCH-USXAA-66N63W /35NENW            Location ID: 306658            Well Name: Wells Ranch-USXAA 35-19            API: 05-123-25078            Location County: Weld County, Colorado            Weather: Partly cloudy.</p> <p>While there, I observed:            Well(s): 1: Temporarily Abandoned   TA.            Battery: Abandoned. ALL equipment has been removed.            Reclamation progressing.            Abandoned Battery SE corner GPS coordinates: 40.447330, -104.408390</p> <p>Abandoned Centralized Battery formerly served 5 Location IDs (306658, 302638, 310088, 310089, 310130).            (Well(s): 5: Temporarily Abandoned   TA).</p> <p>During this inspection, the following possible compliance issues were observed.            1.) Unused Equipment at wellsite. 7 drums motor oil. 2 drip trays.            Refer to Rule 603.f.            Remove 7 drums motor oil, 2 drip trays from Temporarily Abandoned   TA wellsite.            Comply w/ Rule 603.f.            Corrective Action date: 02/18/2020.            See photo #3.</p> <p>A follow up on this site inspection will be conducted to ensure compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/01/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402300976	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055216">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055216</a>
696102083	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055205">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055205</a>