

Inspection Photos

Loc#335548

Operator: Ursa

Inspection Number: 692401859

Inspection Date: 1/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

January 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Weinreis Loc#335548



Photo#2:
Cellar could be fully covered.

January 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Weinreis Loc#335548



Photo#3:
Interim Rec area.



Photo#4:
Interim Rec area.

January 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Dixon Loc#335550