

Inspection Photos

Location Name: WELLS RANCH-65N63W /3NENW

Location #: 332389



Colorado Oil & Gas Conservation Commission
40.43211, -104.42783, 1427.0m, 19°
01/14/2020 04:31:34 PM

Photo #1

Wells Ranch 21-3 Battery site

Abandoned: *Most Equipment removed*

Reclamation progressing

Unused Equipment: *Gas meter run, riser*

. prior insp.



Colorado Oil & Gas Conservation Commission
40.43211, -104.42777, 1433.0m, 7°
02/10/2020 11:05:41 AM

Photo #2

Wells Ranch 21-3 Battery site

Abandoned: *ALL Equipment NOW removed*

Reclamation progressing

Inspection Photos

Location Name: WELLS RANCH-65N63W /3NENW

Location #: 332389



Photo #3

Wells Ranch 21-3 (05-123-22230) Wellsite

Plugged & Abandoned | PA

~ 295 yds.

Reclamation progressing

. prior insp.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources