

Inspection Photos

Location Name: WELLS RANCH-65N63W /10SENW

Location #: 310103



Photo #1

Wells Ranch 22-10 Battery site

Abandoned: *Most Equipment removed*

Reclamation progressing

Wells Ranch 10A, 11, 12, 21-10: Former Battery site

Unused Equipment: 2 Gas meter runs, risers

. prior insp.



Photo #2

Wells Ranch 22-10 Battery site

Abandoned: ALL Equipment NOW removed

Reclamation progressing

Wells Ranch 10A, 11, 12, 21-10: Former Battery site

Inspection Photos

Location Name: WELLS RANCH-65N63W /10SENW

Location #: 310103



Photo #3

Wells Ranch 22-10 (05-123-25910) Wellsite

Plugged & Abandoned | PA

~ 55 yds.

Reclamation progressing

. prior insp.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources