

Inspection Photos

Location Name: WELLS RANCH-65N63W /3NENE

Location #: 332387



Photo #1

Wells Ranch 41-3 Battery site

Abandoned: *Most Equipment removed*

Reclamation progressing

Unused Equipment: *Gas meter run, riser*
prior insp.



Photo #2

Wells Ranch 41-3 Battery site

Abandoned: *Meter house NOW removed*

Reclamation progressing

Riser & Union: Active | In use

Inspection Photos

Location Name: WELLS RANCH-65N63W /3NENE

Location #: 332387



Photo #3

Wells Ranch 41-3 (05-123-22228) Wellsite

Plugged & Abandoned | PA

~ 195 yds.

Reclamation progressing

prior insp.