

Inspection Photos

Location Name: WELLS RANCH-65N63W /2SESW

Location #: 305567



Colorado Oil & Gas Conservation Commission
40.42468, -104.40875, 1412.0m, 327°
01/15/2020 03:41:38 PM

Photo #1

Wells Ranch 24-2, 13-2, 14-2, 23-2 Battery site

Abandoned: *Most Equipment removed*

Reclamation progressing

Unused Equipment: *Gas meter run, riser*
prior insp.



Colorado Oil & Gas Conservation Commission
40.42477, -104.40881, 1405.0m, 307°
02/10/2020 02:33:23 PM

Photo #2

Wells Ranch 24-2, 13-2, 14-2, 23-2 Battery site

Abandoned: *ALL Equipment NOW removed*

Reclamation progressing

Inspection Photos

Location Name: WELLS RANCH-65N63W /2SESW

Location #: 305567



Photo #3

Wells Ranch 24-2 (05-123-23170) Wellsite

Plugged & Abandoned | PA

~ 30 yds.

Reclamation progressing

prior insp.