

Inspection Photos
Location Name: Bergman #1
Location ID: 320471



Photo #1 Tanks



Photo #2 Unmarked produced water tank, separator & meter run

Inspection Photos Location Name: Bergman #1 Location ID: 320471

94 - 960 014

Orifice Plate			Meter		H ₂ S
Date Inspected	Size	Sample	Test Date	Sample Date	
8-15-16	1.250	8-22-16	8-15-16	8-22-16	5.0
8-7-17	1.250	8-7-17	8-7-17	8-7-17	3.5
8-24-17	1.250	No Flow	8-24-17	No Flow	—
8-22-18	1.250	No Flow	8-22-18	No Flow	—
8-20-18	1.250	8-20-18	8-20-18	8-20-18	3.0
2-25-19	1.25	—	2-25-19	2-25-19	—
2-24-19	1.25	—	2-24-19	2-24-19	2.0

Feb 10, 2020 at 11:43:39 AM
 N 39° 59' 4" W 104° 41' 3"

Photo #3 meter card



Photo #4 Unarked wellhead