

Location ID: 450201




Photo #1 Location

Inspection Photos
Location Name: Longhorn U-10 Pad
Location ID: 450201



Photo #2 Tank Battery



Photo #3 Separator & ECD

Inspection Photos
Location Name: Longhorn U-10 Pad
Location ID: 450201



Photo #4 Stain Soil



Photo #5 Stain Soil



Inspection Photos
Location Name: Longhorn U-10 Pad
Location ID: 450201



Photo #6 Full of crude oil



Photo #7 Full of crude oil



Inspection Photos
Location Name: Longhorn U-10 Pad
Location ID: 450201



Photo #8 Stain Soil



Photo #9 Stain Soil

Inspection Photos
Location Name: Longhorn U-10 Pad
Location ID: 450201



Photo #10 Stain Soil



Photo #11 Unused Equipment.

