

**Inspection Photos**  
**Location Name: Mustang 42-34 Pad**  
**Location ID: 453242**



**Photo #1 Location**



**Photo #2 Separator & ECD**

**Inspection Photos**  
**Location Name: Mustang 42-34 Pad**  
**Location ID: 453242**



**Photo #3 Tank Battery**



**Photo #4 Unused Equipment**





**Inspection Photos**  
**Location Name: Mustang 42-34 Pad**  
**Location ID: 453242**



**Photo #5 Unused Equipment**



**Photo #6 Stain Soil**



**Inspection Photos**  
**Location Name: Mustang 42-34 Pad**  
**Location ID: 453242**



**Photo #7 Stain Soil**



**Photo #8 Stain Soil**

