



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Feb 10, 2020 2:17:09 PM MST
Server Receive Date:	Feb 10, 2020 2:17:18 PM MST
Reference Number:	20200210-18132599412
Location:	325 CO-544, Bloomfield, NM 87413, USA Feb 10, 2020 2:16:17 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Jan 16, 2020
Well Name	CUNDIFF GAS UNIT 34-01 1
API Number	50670662600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Removed unused sound walls.

Photo of second corrective action completed



Completed work description of corrective action 2

Replaced BGT produced water sign.

Photo of third corrective action completed



Completed work description of corrective action 3
Completed work description of corrective action 4
Summary of all work completed

Well site sign.

.
Removed unused sound walls and replaced BGT produced water sign.