

**Well Name:** Olson Smith 1  
**API #** 05-067-05455  
**Inspection Number:** 693901379

**Corrective Action:** Removed unused equipment/risers or provide documentation as to why it is needed  
8/19/2019.

**Correction Action Due:** 8/19/2018

**Action Completed:**

**Action Taken:** The equipment does not belong to Catamount Energy, it is Red Cedar & Red Willow

**Corrective Action:** Erosion logs are not installed using good engineering practices (trenched 2 inches into the soil).

**Correction Action Due:** 2/10/2020

**Action Completed:** Trenched in erosion logs.

**Action Taken:** 2/10/2020

Close dog leg is Catamount, the other is Red Cedar



The can belongs to Red Willow, note the Red Willow flag

