

Inspection Photos
Operator: BP America
Location #: 307031
Date: 1-31-2020



Photo 1. View of the monitoring well from the southwestern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Vegetation is largely in a grazed and dormant vegetative condition with grasses such as smooth brome and annual forbs such as sunflower.

St



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of the surrounding reference area, comprised of irrigated grass field. Revegetation within reclamation areas is similar to reference area.