

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/11/2020

Submitted Date:

02/11/2020

Document Number:

701000034

FIELD INSPECTION FORM

Loc ID 338004 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 38 PALMER CREST CT
City: SPRING State: TX Zip: 77381

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291265	WELL	PR	07/06/2007	GW	125-10857	ALLISON 26-16	PR

General Comment:

Routine Inspection

Empty space for additional notes or observations.

Location			
Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Lease signs by meter shed		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Metal panels around VGS and meter shed		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 3		corrective date
Comment:	Shared meter run for (Allison 26-16, Brueggeman 26-15 and 26-1) 590' south of wellhead		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:			Date:

Type: Vertical Separator	# 3		
Comment:	3-Vertical gas separators 50% buried by meter shed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and telemetry equipment at meter shed		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 291265 Type: WELL API Number: 125-10857 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Brueggeman 26-15, 26-1, Allison 26-16\) 590' S of wellhead on north side of CR 25](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT