

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/11/2020

Submitted Date:

02/11/2020

Document Number:

701000037**FIELD INSPECTION FORM**
 Loc ID 303202 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone          | Email                       | Comment |
|--------------|----------------|-----------------------------|---------|
| Jones, Greg  | (970) 630-3909 | greg.jones@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 252659      | WELL | PR     | 06/10/1981  | GW         | 125-06535 | AKEY, M. 1-25 | PR          |

**General Comment:**

Routine Inspection

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Trail through farm ground |       |  |
| Corrective Action: |                           | Date: |  |

Overall Good: ☒

|                      |                                   |       |  |
|----------------------|-----------------------------------|-------|--|
| <b>Signs/Marker:</b> |                                   |       |  |
| Type                 | WELLHEAD                          |       |  |
| Comment:             | Lease sign by unit                |       |  |
| Corrective Action:   |                                   | Date: |  |
| Type                 | OTHER                             |       |  |
| Comment:             | Lease signs mounted to metal shed |       |  |
| Corrective Action:   |                                   | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Vertical Separator  | # 0   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Gas Meter Run       | # 2   |       |                 |
| Comment:                  | Shared meter run for (Akey, M 1-25 and Acker 14-25) 550' west of wellhead |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Pump Jack           | # 1   |       |                 |
| Comment:                  | Jensen unit   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Prime Mover         | # 1   |       |                 |
| Comment:                  | Electric motor  |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Ancillary equipment | # 1   |       |                 |
| Comment:                  | Electric panel  |       |                 |
| Corrective Action:        |   | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |  |       |      |             |           |         |    |               |    |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 252659   | Type: | WELL | API Number: | 125-06535 | Status: | PR | Insp. Status: | PR |
| Producing Well       |  |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production. Central meter run for (Acker 14-25 and Akey 1-25) 550' W of wellhead |       |      |             |           |         |    |               |    |
| Corrective Action:   |  |       |      |             |           |         |    | Date:         |    |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Other                   | Pass                  |               |                          |         |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT