

Inspection Photos
Location Name: Genesis 3, 9-2
Location ID: 319579



Photo 1: Wellhead; NO SIGNAGE



Photo 2: Unused equipment



Inspection Photos
Location Name: Genesis 3, 9-2
Location ID: 319579



Photo 3: Wellhead; NO SIGNAGE



Photo 4: Unused equipment

Inspection Photos
Location Name: Genesis 3, 9-2
Location ID: 319579



Photo 5: Unused equipment



Photo 6: Maintenance tank not in containment, doesn't appear to be grounded, weeds

Inspection Photos
Location Name: Genesis 3, 9-2
Location ID: 319579



Photo 7: Unused equipment, weeds



Photo 8: Unused equipment

Inspection Photos
Location Name: Genesis 3, 9-2
Location ID: 319579



Photo 9: Tank Battery Sign



Photo 10: Tank Battery

Inspection Photos
Location Name: Genesis 3, 9-2
Location ID: 319579



Photo 11: Inadequate berm walls



Photo 12: Inadequate berm walls

Inspection Photos
Location Name: Genesis 3, 9-2
Location ID: 319579



Photo 13: Unused equipment in gas meter house



Photo 14: Unused riser

Inspection Photos
Location Name: Genesis 3, 9-2
Location ID: 319579



Photo 15: Unused risers/equipment



Photo 16: Tank appears to not be grounded

