

Inspection Photos
Operator: BP America
Location #: 333471
Date: 1-31-2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of wood debris and junk that remains in the northeastern project area.



Photo 3. View of the western project area from the southwestern corner facing northward. Vegetation is progressing in a dormant vegetative condition with grasses such as crested wheatgrass and intermediate wheatgrass.



Photo 4. View of the reference area, comprised of pinyon juniper woodland with annual grasses and forbs in the largely grazed understory.