

Inspection Photos
Location Name: Rainbow #1
Location ID: 320117



Photo #1 tank



Photo #2 separator and meter run

Feb 11, 2020 at 12:39:17 PM
N 39° 59' 5" W 104° 41' 28"
144° S
Adams County Inspection

Inspection Photos
Location Name: Rainbow #1
Location ID: 320117

Station #	Ad	Gr	Station Name	RAINBOW #1	Sec	TwnShip	Range
30338	182	55	Producer Name	Great West Energy	8	1S	65W
176-9176	Federal #		State #	Mtr Tube Size 3.068"			
17953079	State #		County Adams				
Static / Span	Up / Dwn	Diff / Span	Temp / Span	Absolute	API # 62582		
0-300#		0-250"	0-150°F	12.2	3/24/0100		
Test Date	OP Size	Beta	Sample Date	H ₂ S	Sample Date	H ₂ S	Gravity
1/7/11	1.250		Lastrol 50	Roc			
4/5/11	1.250		4/5/11	2.0			
10/14/11	1.250		10/14/11	2.0			
4/16/12	1.250		4/16/12	2.0	5/18/12	2.0	
10/30/12	1.250		10/30/12	3.0			
4/19/13	1.250		4/19/13	2.0			
10/10/13	1.250		10/10/13	4.0			
4/16/14	1.250		4/16/13	3.6			
10/23/14	1.250		10/23/14	3.0			
4-23-15	1.250 ✓		no sample				
10-28-15	1.25		10-28-15	2.0			
4-14-16	1.25						
5-24-18	1.250 ✓						
6-18-19	1.500 ✓		6-18-19	4.0			
			R+L				



Photo #3 calibrated meter card

Photo #4 used bucket in separator house

Inspection Photos
Location Name: Rainbow #1
Location ID: 320117



Photo #5 wellhead