

Inspection Photos

API: 071-07894

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/10/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07894 | Date: 2/10/2020

Inspection Photos



Photo 1. The cattle guard at the beginning of the access road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07894 | Date: 2/10/2020

Inspection Photos



Photo 2. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07894 | Date: 2/10/2020

Inspection Photos



Photo 3. Well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07894 | Date: 2/10/2020