

Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Photo 1 – Tank Battery



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179




Photo 3 – Unmarked Risers East of ECD



Photo 4 – Unmarked Risers East of Heater Shed



Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Photo 5 – Unused Loadline and Bucket




Photo 6 – Unused pipes and fittings East of berm

Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Photo 7 – Missing Capacity Label




Photo 8 – Unused Stand at Pumping Unit