

Inspection Photos

API: 071-09769

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/10/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09769 | Date: 2/10/2020

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09769 | Date: 2/10/2020

Inspection Photos



Photo 2. Vegetation appears to be established in the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09769 | Date: 2/10/2020

Inspection Photos



Photo 3. Well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09769 | Date: 2/10/2020

Inspection Photos



Photo 4. Facing east toward the fill slope and sediment trap.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09769 | Date: 2/10/2020