

Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 11/25/2019



Photo # 1 –

Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 11/25/2019



Photo # 2 – Concrete separator foundation, requires removal and proper disposal

Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 11/25/2019



Photo # 3 – Stock tanks remain on location.



Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 11/25/2019



Photo # 4 – Risers require proper abandonment. Located on west side of pit ID 107649.

Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 11/25/2019



Photo # 5 – Pit ID 107649 view north .



Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 11/25/2019



Photo # 5 – Pit ID 119049 view north .

