

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402303227
Receive Date:
02/11/2020
Report taken by:
Jason Kosola

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation. Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: EVERGREEN NATURAL RESOURCES LLC	Operator No: 10705	Phone Numbers Phone: (719) 846-7898 Mobile: ()
Address: 1801 BROADWAY SUITE 350		
City: DENVER	State: CO	Zip: 80202
Contact Person: Cheri Morgan	Email: cheri.morgan@enrllc.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION
Remediation Project #: 15097 Initial Form 27 Document #: 402303227

PURPOSE INFORMATION

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other _____

SITE INFORMATION N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: SPILL OR RELEASE	Facility ID: 470542	API #: _____	County Name: LAS ANIMAS
Facility Name: Lorencito 7-7	Latitude: 37.100980	Longitude: -104.813800	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SENE	Sec: 7	Twp: 34S	Range: 66W
		Meridian: 6	Sensitive Area? No

SITE CONDITIONS

General soil type - USCS Classifications CL Most Sensitive Adjacent Land Use Non crop land

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Nearest water well - 429.5' (if DWR point is accurate) nearest surface water - 178' (if live water present)

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	1 to 3 inches	Soil Samples

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Produced water from several wells was being stored in this offsite pit associated to a DCPS permitted surface discharge outfall Lorencito 7-7 No.005 outfall Permit #CO-0047776

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Evergreen plans to resample the affected area. Evergreen will work with our third-party contractor to establish a compliance point at or near the suggested location to get native samples around the spill path and samples where SS1, SS3 & SS4 came back with impacts above COGCC Table 910-1.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 4
Number of soil samples exceeding 910-1 3
Was the areal and vertical extent of soil contamination delineated? No
Approximate areal extent (square feet) 0

NA / ND

-- Highest concentration of TPH (mg/kg) 68
-- Highest concentration of SAR 18
BTEX > 910-1 No
Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet) 0
Number of groundwater monitoring wells installed 0
Number of groundwater samples exceeding 910-1 0

Highest concentration of Benzene (µg/l) 0
Highest concentration of Toluene (µg/l) 0
Highest concentration of Ethylbenzene (µg/l) 0
Highest concentration of Xylene (µg/l) 0
Highest concentration of Methane (mg/l) 0

Surface Water

0 Number of surface water samples collected
0 Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

At the agency's request Evergreen is preparing an initial remediation plan that will consists of first re-sampling the area, then if needed, developing a follow-up remediation plan based on the samples.

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Lines were capped to prevent further discharge

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

See attachment with this form 27 for visual reference. Evergreen proposes to collect samples within the affected spill area, where the brown circles indicate previous soil samples, SS sites 1, 3 and 4 that had high results in SAR will be resampled. Native samples will be collected from surrounding the spill area. All samples will be taken at least 1 foot below surface and lab tested for our usual 910-1 standards. All soil sample results and their GPS location will be submitted to the COGCC for review.

Soil Remediation Summary

In Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

Ex Situ

- _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____
- _____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: Quarterly Semi-Annually Annually Other _____

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The need for reclamation is dependent on the results of the proposed site soil sample investigation plan attached.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim? Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 01/02/2020

Actual Spill or Release date, if known. 01/02/2020

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/02/2020

Date of commencement of Site Investigation. _____

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Evergreen plans to resample the affected area. Evergreen will work with our third-party contractor to establish a compliance point at or near the suggested location to get native samples around the spill path and samples where SS1, SS3 & SS4 came back with impacts above COGCC Table 910-1. These results will be shared with the agency as they become available to Evergreen Natural Resources.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Cheri Morgan _____

Title: Regulatory Coord. _____

Submit Date: 02/11/2020 _____

Email: cheri.morgan@enrllc.com _____

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jason Kosola _____

Date: 02/13/2020 _____

Remediation Project Number: 15097 _____

COA Type**Description**

	<p>1)Operator shall conduct additional soil sampling from SS 1, SS 3 and SS4 within 180 days of spill (June 30, 2020) and submit to the Commission via eForm 27 Supplemental within 25 days of obtaining samples. Operator shall provide soil sample location coordinates for record. Soil samples shall be collected from top 1-3 inches of soil.</p> <p>2)Operator shall submit eForm 19 Supplemental requesting closure of Spill 470542 no later than February 21, 2020.</p>
--	---

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402303227	FORM 27-INITIAL-SUBMITTED
402306511	SOIL SAMPLE LOCATION MAP
402309431	ANALYTICAL RESULTS

Total Attach: 3 Files

General Comments**User Group****Comment****Comment Date**

Environmental	Operator re-submitted Form 27 assigned to spill.	02/13/2020
Environmental	Returned to DRAFT Remediation is assigned to pit. Remediation is in response to a spill. Operator shall submit F27 and assign to a spill.	02/11/2020

Total: 2 comment(s)