

Inspection Photos
Operator: BP America
Location #: 325591
Date: 2/13/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing within the interim reclamation area with smooth brome, thickspike wheatgrass, and sand dropseed. Scattered musk thistles observed.



Photo 3. View of the reference area, comprised of irrigated grass field.