

Inspection Photos
Operator: BP America
Location #: 334000
Date: 2/13/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing here with western wheatgrass, crested wheatgrass, and intermediate wheatgrass.



Photo 3. View of the reference area, comprised of pinyon and juniper woodland with sagebrush and herbaceous understory.