

Inspection Photos  
Operator: BP America  
Location #: 306798  
Date: 2/13/2020



Photo 1. View of the project area from the northwestern corner facing center.





Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing here with western wheatgrass and crested wheatgrass.



Photo 3. View of the southern project area from the southwestern corner facing eastward.





Photo 3. View of the reference area, comprised of irrigated grass field. Irrigation appears to be diverted around well pad.