

Inspection Photos

ALs Loc#419862

Operator: Terra

Inspection Number: 692401881

Inspection Date: 1/31/2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to North.

January 31,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra ALs Mead Loc#419862



Photo#2:
Risers at East end of Well Line Up.

January 31, 2020