

# *Inspection Photos*

*Loc#419862*

*Operator: Terra*

*Inspection Number: 692401888*

*Inspection Date: 1/31/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from Entry.

January 31, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#2:  
Weedy Interim area.



Photo#3:  
Weedy Interim area

January 31, 2020





Photo#4:  
Weedy area of Cut.




Photo#5:  
Weedy area at BMP.

January 31, 2020





Photo#6:  
Weeds in irrigated area.



Photo#7:  
Weeds in irrigated area.

January 31, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862