

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2020

Submitted Date:

02/07/2020

Document Number:

699100998**FIELD INSPECTION FORM**Loc ID 440858 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440858	LOCATION	AC			-	Simpson FD Pad 15-219HN	AC

General Comment:

Inspected Facilities

Facility ID: 440858 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Corrective Action:

Date:

Complaint

Comment:

Inspection in response to complaint.
 Field Inspector Assigned: Adam Burns
 Complaint Received
 Date: 02-3-2020
 Complaint Contacted: N/A
 Location ID #440858
 Inspection Document # 699100998
 18. Complaint Document # N/A
 Nature of Complaint: Noise
 Field Inspector Actions:
 On 01-31-2020, I Adam Burns area field inspector was assigned a complaint (low frequency, vibration) received by COGCC staff in reference to Noise. The complainant contacted my supervisor, Adam Kraich via phone call to report the complaint. The complainant was directed to file a complaint with the commission on the COGCC website.
 On 01/31/2020, I along with supervisor Adam Kraich set a sound meter at 562 Cherry Lane, in Windsor CO. 40.48687, -104.87346. The sound audit began 1/31/2020 and ended 2/3/2020. Only nighttime (21:00 to 08:00) hours were used in the study. Additionally, the only usable data in the study was 1/31/2020 to 2/1/2020, as wind speed is beyond 5mph for the remaining dates.
 The resulting data from the study, is an LEQ 2 of 72.1 DB, which suggest noncompliance of rule 802.d.
 See report for corrective action detail.
 See attachments for sound audit, and weather detail.
 All information reviewed and site inspection information were submitted to the COGCC for further review.
 END OF REPORT

Corrective Action: comply with rule 802.d.

Date: 03/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402306641	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060703
699101014	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060692
699101037	Sound Study	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060693
699101038	Weather Data	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060694