

Put on Computer

CHECK FOR
INTENT

w/m JAMS A/L

BEST IMAGE
AVAILABLE

WELL SITE INSPECTION FORM



LOCATION SESE 23-15S-46W

FIELD GRADISE

OPERATOR Amoco

COUNTY CHEYENNE

WELL NAME #7 Champion 205 Amoco A'

PERMIT # 84-1141

DATE OF INSPECTION DURING DRILLING: _____

RIG _____

SURFACE CASING: _____

DEPTH: _____

BOP'S _____

RETURNS: _____

WOC: _____

CONTACT _____

CMT VOL: _____

ADEQUATE AQUIFER PROTECTION? _____

COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: YES _____ NO _____

PRODUCTION STRING: _____

WATER DISPOSAL: PITS _____, INJECTED _____, COMMERCIAL _____, UNKNOWN _____, N.A. _____

PITS: PERMIT Y _____ N _____, SKIM TANK Y _____ N _____, DIMENSIONS _____

LEASE SIGN: YES _____ NO _____ TANK ID: YES _____ NO _____ NA _____ FENCED: YES _____ NO _____

SURFACE EQUIPMENT: _____

COMMENTS: _____

DATE OF P&A INSPECTION 11/4/86

PITS BACKFILLED: YES ☒ NO ☐

SURFACE RECLAIMED: YES ☒ NO ☐

HOLE MARKER: YES ☐ NO ☒

SITE CLEAN: YES ☒ NO ☐

BOND RELEASE OK: YES ☒ NO ☐

LANDOWNER RELEASE: YES ☐ NO ☐

COMMENTS: CASING & WELLHEAD GONE - SITE LEVELLED & DRILLED IN WHAT?

DATE OF SAFETY INSPECTION _____

COMMENTS: _____

INSPECTOR J. VACLAVIK

API No. 03-017' 6474

P&A Inspected: Yes ☒ No ☐