

Ward & Son Alfred, Kloefkorn 1
121-09045

Inspection #688306985

2/14/2020

High Risk Inspection



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Colorado Oil and Gas Conservation Commission

39.82472, -103.35224, 4842.5ft, 339°

02/14/2020 02:36:32 PM



New dirt at wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Colorado Oil and Gas Conservation Commission
39.82481, -103.35208, 4842.5ft, 334°
02/14/2020 02:36:48 PM



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Colorado Oil and Gas Conservation Commission

39.82477, -103.35207, 4836.0ft, 318°

02/14/2020 02:36:57 PM



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.8248, -103.35208, 4845.8ft, 33°
02/14/2020 02:36:52 PM



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Colorado Oil and Gas Conservation Commission

39.82647, -103.34343, 4832.7ft, 40°

02/14/2020 01:49:51 PM



18077

181341

CRUDE OIL
300 BIBLS

C 479 14

18 342

Colorado Oil and Gas Conservation Commission

39.82646, -103.34343, 4862.2ft, 28°

02/14/2020 01:49:57 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Colorado Oil and Gas Conservation Commission
39.82646, -103.34336, 4865.5ft, 349°
02/14/2020 01:50:09 PM




COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Treater has propane tank.

Colorado Oil and Gas Conservation Commission
39.82645, -103.34337, 4858.9ft, 187°
02/14/2020 01:50:13 PM



No content or quantity label on front of tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Colorado Oil and Gas Conservation Commission

39.82609, -103.34341, 4849.1ft, 46°

02/14/2020 01:51:01 PM



No quantity
label on tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Colorado Oil and Gas Conservation Commission
39.82608, -103.34339, 4852.4ft, 138°
02/14/2020 01:51:05 PM



Free oil spill on pit
with stained soil
around inside
edges of pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Colorado Oil and Gas Conservation Commission

39.82595, -103.34358, 4832.7ft, 46°

02/14/2020 02:29:32 PM



Colorado Oil and Gas Conservation Commission

39.82603, -103.34339, 4839.2ft, 157°

02/14/2020 01:51:17 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.82601, -103.34338, 4842.5ft, 177°

02/14/2020 01:51:30 PM



Colorado Oil and Gas Conservation Commission

39.82601, -103.34337, 4842.5ft, 229°

02/14/2020 01:51:34 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Colorado Oil and Gas Conservation Commission

39.82602, -103.34344, 4845.8ft, 258°

02/14/2020 01:51:44 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.82574, -103.34375, 4813.0ft, 157°
02/14/2020 01:55:36 PM

Stained soil piles are gone.

Colorado Oil and Gas Conservation Commission
39.82601, -103.34358, 4865.5ft, 353°
02/14/2020 02:29:43 PM

Old skim pit area.

Colorado Oil and Gas Conservation Commission
39.82608, -103.34358, 4858.9ft, 121°
02/14/2020 02:29:54 PM