

Ward & Son Alfred, Wright 31-1
121-09464

Inspection #688306986

2/14/2020

Routine Inspection



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Colorado Oil and Gas Conservation Commission

39.82841, -103.35229, 4868.8ft, 346°

02/14/2020 02:45:39 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



New dirt at
wellhead.

Colorado Oil and Gas Conservation Commission
39.82837, -103.35224, 4852.4ft, 358°
02/14/2020 02:45:59 PM



Stained soil
at edge of
new dirt.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Colorado Oil and Gas Conservation Commission
39.82837, -103.35227, 4858.9ft, 35°
02/14/2020 02:45:48 PM



COLORADO
**Oil & Gas Conservation
Commission**
Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.82832, -103.35222, 4858.9ft, 333°
02/14/2020 02:46:07 PM



Colorado Oil and Gas Conservation Commission

39.82753, -103.35059, 4852.4ft, 143°

02/14/2020 02:47:03 PM

Landfarming soils are removed.

Colorado Oil and Gas Conservation Commission

39.82756, -103.3502, 4845.8ft, 164°

02/14/2020 02:49:13 PM

Old skim pit is gone.

Colorado Oil and Gas Conservation Commission

39.82755, -103.35059, 4849.1ft, 80°

02/14/2020 02:46:59 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.82762, -103.35023, 4849.1ft, 338°
02/14/2020 02:48:05 PM