

COLORADO O



99999999

ION COMMISSION
ORT☐ NOTICE OF UNSATISFACTORY INSPECTION☒ NOTICE OF SATISFACTORY INSPECTION1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05-

075 - 6128

LEASE NAME:

Knudsen 1

LOCATION:

NENENE 6-8N-52

OPERATOR:

MiLinda

DATE:

9-8-97

INSPECTOR:

Ed Bickley (970) 842-4165

Insp. Type: HR

Insp. Status: DA

PA: Y

N

Pass/Fail: P

F

Viol.: Y

N

NOV: Y

N

INSPECTION ITEM

COMMENTS

INPUT

| | | |
|--|-------|--|
| Well ID Signs (Rule 210, 604.c(4)) | | |
| Pits (Reserve/Production) (Rule 902, 903, 904, 905) | | |
| Fences (Rule 603.b.7, 604.C.(3), 1002.A) | | |
| Tank Battery Equipment (Rule 603.b.3, 604) | | |
| Fire Walls/Berms/Dikes (Rule 603.b.12, 604) | | |
| General Housekeeping (Rule 603) | | |
| Spills (Oil/Water) (Rule 907) | | |
| Bradenhead (Rule 207.b) | | |
| Drilling Well/Workover (Rule 317) | | |
| Surface Rehabilitation (Rule 1002, 1003, 1004, 1103) | grass | |
| Miscellaneous | | |

CORRECTIVE ACTION REQUIRED:



00235100

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

SEP 25 1997