

Inspection Photos

API: 071-07675

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07675 | Date: 2/14/2020

Inspection Photos



Photo 1. Facing east along side of the main access road. Erosion repairs have been made since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07675 | Date: 2/14/2020

Inspection Photos



Photo 2. Facing southeast along the access road. Rock rip/rap has been placed along the side and gravel on the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07675 | Date: 2/14/2020

Inspection Photos



Photo 3. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07675 | Date: 2/14/2020

Inspection Photos



Photo 4. Well sign is installed at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07675 | Date: 2/14/2020