

# Inspection Photos

API: 071-08183

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/14/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08183 | Date: 2/14/2020

## Inspection Photos



**Photo 1.** Stormwater drainage from the main road is causing erosion near the culvert at Lat/Long:37.13600,-104.83819.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08183 | Date: 2/14/2020

## Inspection Photos



**Photo 2.** Facing toward the location.



## Inspection Photos



**Photo 3.** Well sign is installed at meter shed. Old operator sign (red arrow) should be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08183 | Date: 2/14/2020