

Inspection Photos

Location Name: J&L FARMS-66N63W /30SWNE

Location #: 332073



Photo #1

J&L Farms 32-30 (05-123-21801) Wellsite

Plugged & Abandoned | PA

~ 25 yds.

Reclamation progressing



Photo #2

J&L Farms 32-30, 31-30 Battery site

Abandoned: *ALL Equipment removed*

Reclamation progressing

Fencing belongs to landowner