


COLORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

MAY 11 1996



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	1120 Lincoln Street Denver (303)
API No. 05-017 - 7513	LEASE NAME: RED ROCKS #1-20
LOCATION: NESW 20-155-42W	OPERATOR: Amoco
DATE: 4-3-96	INSPECTOR: R. VanSickle
Insp. Type: CA	Insp. Status: DA
PA: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	Pass/Fail: P <input checked="" type="checkbox"/> F <input type="checkbox"/>
Viol.: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	NOV: Y <input type="checkbox"/> N <input type="checkbox"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	✓	
Pits (Reserve/Production) (Rule 902, 903, 904)	✓	
Fences (Rule 604.C.(3), 1003.A)	✓	
Tank Battery Equipment (Rule 604)	✓	
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)	On loc. @ 0010 HRS. Pump first plug, 40 sk @ 4996'. Pull pipe to 2351' & set	✓
Surface Rehabilitation (Rule 317)		
Miscellaneous	40 sk plug. Pull pipe to 1886', set 40 sk plug. Pull pipe to 1514' & set 40 sk plug. Pull pipe to 619', set 40 sk plug. Pull pipe to 60', set 10 sk. Left 05/20/96	✓



CORRECTIVE ACTION REQUIRED: None.

Date Corrective Action Required By: _____ Date Remedied: _____

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.