

Inspection Photos

API: 071-09291

Operator: TIMBER CREEK OPERATING

Inspection Date: 2/18/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09291 | Date: 2/18/2020

Inspection Photos



Photo 1. Facing toward the location. Vegetation appears to be well established in the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09291 | Date: 2/18/2020

Inspection Photos




Photo 2. There is oil in the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09291 | Date: 2/18/2020

Inspection Photos



Photo 3. well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09291 | Date: 2/18/2020