

Inspection Photos

Location Name: J & L FARMS-66N63W /29NESW

Location #: 331314



Colorado Oil & Gas Conservation Commission
40.4536, -104.4656, 1405.0m, 104°
02/19/2020 03:23:46 PM

Photo #1

J & L Farms 29B (05-123-20483) Wellsite

Plugged & Abandoned | PA

~ 30 yds.

Reclamation progressing



Colorado Oil & Gas Conservation Commission
40.45596, -104.46094, 1405.0m, 273°
02/19/2020 03:40:16 PM

Photo #2

J&L Farms 22-29 Battery site

Inactive | Shut-down

Formerly served:

J&L Farms 12-29, 13-29, 23-29, 33-29, 29B

(Plugged & Abandoned | PA)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources