

Construction and Stormwater Inspection

February 13, 2020

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 470863

Inspection Document #: 697501113

Weld County, CO

SESE Section 23 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Photo taken from the northern location, facing West. Photo illustrates Operator has installed a ditch and berm BMP. The berm BMP still needs to be stabilized and the Operator had plans to conduct this work the following Monday.

Note: whatever BMP the Operator installs during construction activities shall be in proper functioning condition prior to topsoil salvage operations (i.e., berm should have already been stabilized).

Inspection Photos
Location Name: North Platte /T-23 Pad
Location ID: 470863



Photo 2. Photo taken from the northern location, facing South. Photo illustrates Operator is in-process for constructing the location to grade.

Inspection Photos

Location Name: North Platte /T-23 Pad

Location ID: 470863



Photo 3. Photo taken from the western perimeter of location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: North Platte /T-23 Pad
Location ID: 470863



Photo 4. Photo taken from the southwestern perimeter of location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: North Platte /T-23 Pad
Location ID: 470863



Photo 5. Photo taken from the southeastern perimeter of location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: North Platte /T-23 Pad
Location ID: 470863



Photo 6. Photo taken from the eastern perimeter of location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: North Platte /T-23 Pad
Location ID: 470863



Photo 7. Photo taken from the eastern perimeter of location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: North Platte /T-23 Pad
Location ID: 470863



Photo 8. Photo taken from the northeastern perimeter of location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: North Platte /T-23 Pad
Location ID: 470863



Photo 9. Photo taken from the eastern perimeter of location, facing Southeast. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.