

# Interim Reclamation and Stormwater Inspection

February 18, 2020

Operator: VERDAD RESOURCES LLC - # 10651

Location ID: 439116

Inspection Document #: 697501121

Weld County, CO

NWNW Section 2 T1N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Pastelak 01N-64W-02  
Location ID: 439116



**Photo 1.** Photo taken from the location, facing West. Photo illustrates only one well has been drilled. Photo also illustrates interim reclamation activities to reduce all areas only need for production operations have been completed. COGCC staff will have to perform a future inspection to evaluate vegetative compliance.

Inspection Photos  
Location Name: Pastelak 01N-64W-02  
Location ID: 439116



**Photo 2.** Photo taken from the location, facing Northwest. See comments under Photo 1.



Inspection Photos  
Location Name: Pastelak 01N-64W-02  
Location ID: 439116



**Photo 3.** Photo taken from the northeastern location, facing North. Photo illustrates unused equipment at location.