

# Inspection Photos

API: 071-08143

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/19/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08143 | Date: 2/19/2020

## Inspection Photos



**Photo 1.** Facing southeast toward the location. Vegetation is well established in the interim reclamation area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08143 | Date: 2/19/2020

## Inspection Photos



**Photo 2.** Well sign is posted at the meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08143 | Date: 2/19/2020