

Location Name: – Peterson Energy Operating – Church Battery –Spill ID 471632
Inspection Date: 02/18/2020




Photo # 1 –

Location Name: – Peterson Energy Operating – Church Battery –Spill ID 471632
Inspection Date: 02/18/2020



Photo # 2 – View north along east side of tank battery. Vacuum truck removing accumulated oil



Location Name: – Peterson Energy Operating – Church Battery –Spill ID 471632
Inspection Date: 02/18/2020



Photo # 3 – View north along west side of tank battery. Vacuum truck removing accumulated oil

Location Name: – Peterson Energy Operating – Church Battery –Spill ID 471632
Inspection Date: 02/18/2020



Photo # 4 – View northeast at plastic staged for impacted soil stockpile

