

# Final Reclamation Inspection

February 18, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 319134

Inspection Document #: 697501128

Weld County, CO

SESW Section 3 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MURPHY #1  
Location ID: 319134



**Photo 1.** Photo taken from the PA well location, facing Northwest. Photo illustrates PA access road is still in use for a temporarily abandoned well.

Inspection Photos  
Location Name: MURPHY #1  
Location ID: 319134



**Photo 2.** Photo taken from the PA well location, facing Southeast. See comments under Photo 1.

Inspection Photos  
Location Name: MURPHY #1  
Location ID: 319134



**Photo 3.** Photo taken from the tank battery location, facing East. Photo illustrates portions of the tank battery have been reclaimed but equipment remains.

Inspection Photos  
Location Name: MURPHY #1  
Location ID: 319134



**Photo 4.** Photo taken from the tank battery location. Photo illustrates a meter house no longer in use.



**Photo 5.** COGCC COGIS Online aerial imagery from 2017 illustrates a spill area circled in red. COGCC staff will have to perform a follow up inspection to ensure spill area meet Rule 1004 vegetation standards.