

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Gunderson /29-09 Pad

Location ID: 334426



**Photo #0618 from entrance to location**



**Photo #0615 Multiple places with paraffin and oily fluids in tank containment.**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Gunderson /29-09 Pad

Location ID: 334426



**Photo #0616 Multiple places with paraffin and oily fluids in tank containment.**



**Photo #0617 Multiple places with paraffin and oily fluids in tank containment.**