

Inspection Photos

Location Name: BEAN 33-26 FOLLOWUP

API#: 05-071-07640

INSP. #: 695102194



Colorado Oil & Gas Conservation Commission
37.13694, -104.84863, 2098.0m, 252°
2020/02/20 14:08:48

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.13697, -104.84863, 2106.0m, 334°
2020/02/20 14:09:07

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: BEAN 33-26 FOLLOWUP
API#: 05-071-07640
INSP. #: 695102194

Calibration Report

Report Date: 3/21/19 9:43 AM Collection Time: 3/21/19 9:52 AM

Device ID: 100107675 System: Contact # 719-646-7811
Location: SAURIA 44-35 Field: Raton Basin
State: Colorado
Producer: Evergreen Natural Gas
Purchaser: Colorado Interstate Gas

Current Date Size: 0.500 Tap Type: Flange
Pipe Size: 2.000 SP Tap Location: Crown 95.000
Airline Pressure: 11.40 Temperature Base: 60
Pressure Base: 14.73

Plate Inspected? ☐ Yes ☒ No Dirty? ☐ Yes ☒ No Nipped? ☐ Yes ☒ No
Edges Sharp? ☐ Yes ☒ No Plate Mic'd? ☐ Yes ☒ No Warped? ☐ Yes ☒ No
Seal Ring Damaged? ☐ Yes ☒ No Pitted? ☐ Yes ☒ No Bore Downstream? ☐ Yes ☒ No
Tube Inspected? ☐ Yes ☒ No Nipped? ☐ Yes ☒ No
Dirty? ☐ Yes ☒ No Pitted? ☐ Yes ☒ No

DIFFERENTIAL				STATIC PRESSURE			
FOUND	LEFT	FOUND	LEFT	FOUND	LEFT	FOUND	LEFT
0.00	0.00	0.00	11.40	11.50	11.40	11.50	11.50
20.00	20.01	20.01	12.40	12.51	12.40	12.51	12.51
35.00	35.03	35.03	61.40	61.42	61.40	61.42	61.42
50.00	50.06	50.06	111.40	111.54	111.40	111.54	111.54
75.00	75.09	75.09					
100.00	100.13	100.13					

Cal. Range: 0 0 0
100 112 150

Gas Sample Taken? ☐ Yes ☒ No
H2S analysis done? ☐ Yes ☒ No
PPM: 0%

H2O Analysis (ppm): 0

REMARKS: 37.13704, -104.84866, 2105.0m, 318°
2020/02/20 14:09:42

PHOTO 1: LOCATION

