

Location Name: – Ward and Son Operating – Blomenkamp 4 (121-05567)
Inspection Date: 02/18/2020



Photo # 1 –

Location Name: – Ward and Son Operating – Blomenkamp 4 (121-05567)
Inspection Date: 02/18/2020



Photo # 2 – View south inside former flowline leak (Active Spill ID 459536) excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Ward and Son Operating – Blomenkamp 4 (121-05567)
Inspection Date: 02/18/2020



Photo # 2 – View south at lined emergency pit (requires Form 27 for closure)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Ward and Son Operating – Blomenkamp 4 (121-05567)
Inspection Date: 02/18/2020



Photo # 4 – View north near wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Ward and Son Operating – Blomenkamp 4 (121-05567)
Inspection Date: 02/18/2020



Photo # 5 – View north near wellhead, impacted soil stockpiles adjacent to excavation