

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/21/2020

Submitted Date:

02/21/2020

Document Number:

700700155**FIELD INSPECTION FORM**
 Loc ID 335120 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10531Name of Operator: GRIZZLY OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:25 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		scollett@grizzlyenergyllc.com	
, Grizzly		aaxelson@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291271	WELL	PR	11/20/2007	GW	045-14322	GEISKE 43C-26-692	PR
291273	WELL	PR	11/21/2007	GW	045-14323	GEISKE 42A-26-692	PR
291308	WELL	PR	05/09/2013	GW	045-14330	GEISKE 32B-26-692	PR
291314	WELL	PR	11/24/2007	GW	045-14325	GEISKE 32D-26-692	PR
297963	WELL	PR	05/21/2009	GW	045-17004	GEISKE 41B-26-692	PR
297964	WELL	PR	05/21/2009	GW	045-17005	GEISKE 41A-26-692	PR
297965	WELL	PR	05/15/2009	GW	045-17006	GEISKE 42C-26-692	PR
297966	WELL	PR	05/15/2009	GW	045-17007	GEISKE 42D-26-692	PR
297967	WELL	PR	05/15/2009	GW	045-17008	GEISKE 43D-26-692	PR
297968	WELL	PR	05/18/2009	GW	045-17009	GEISKE 32C-26-692	PR
297969	WELL	PR	05/18/2009	GW	045-17010	GEISKE 42B-26-692	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 2/21/20 at approximately 10:30 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Grizzly Gieski, at Location # 335120 in Garfield Colorado.

While there, I observed normal production operations. All C/A(s) from document # 694900416 and document # 694900617 have been completed.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	All signs represent current operator		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	All signs represent current operator		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	All signs represent current operator		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	All signs represent current operator		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	staining has been removed		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Gas Meter Run	# 4			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	chemical tanks			
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 12			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 13			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 6			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 11			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heater Treater	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	300 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	2 tanks are in a seperate containment			
Corrective Action:				
			Date:	

<u>Venting:</u>			
Yes/No	NO		
Comment:	All braden heads are shut		
Corrective Action:		Date:	

<u>Flaring:</u>			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	291271	Type:	WELL	API Number:	045-14322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291273	Type:	WELL	API Number:	045-14323	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291308	Type:	WELL	API Number:	045-14330	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291314	Type:	WELL	API Number:	045-14325	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297963	Type:	WELL	API Number:	045-17004	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297964	Type:	WELL	API Number:	045-17005	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297965	Type:	WELL	API Number:	045-17006	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297966	Type:	WELL	API Number:	045-17007	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	297967	Type:	WELL	API Number:	045-17008	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	297968	Type:	WELL	API Number:	045-17009	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	297969	Type:	WELL	API Number:	045-17010	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700160	photos for Gieski	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5074590