

Location Name: – Ward and Son Operating – Pierce #3 (121-05637)

Inspection Date: 02/18/2020



Photo # 1 –



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Ward and Son Operating – Pierce #3 (121-05637)
Inspection Date: 02/18/2020



Photo # 2 – Hydrophobic soil just south of the wellhead

Location Name: – Ward and Son Operating – Pierce #3 (121-05637)
Inspection Date: 02/18/2020



Photo # 3 – Hydrophobic soil and discolored soil and vegetation south of the wellhead

Location Name: – Ward and Son Operating – Pierce #3 (121-05637)
Inspection Date: 02/18/2020



Photo # 4 – Bare soil and equipment tracks north of the wellhead (beyond area noted on FI 688301165 2/14/2018)

Location Name: – Ward and Son Operating – Pierce #3 (121-05637)
Inspection Date: 02/18/2020



Photo # 5 –

Location Name: – Ward and Son Operating – Pierce #3 (121-05637)
Inspection Date: 02/18/2020



Photo # 6 –

Location Name: – Ward and Son Operating – Pierce #3 (121-05637)
Inspection Date: 02/18/2020



Photo # 7 –



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources