

Banta Ridge 3  
API: 05-103-07513  
Inspection: 700400133



**Photo 1. Location.**

Banta Ridge 3  
API: 05-103-07513  
Inspection: 700400133



**Photo 2. Well head.**



Banta Ridge 3  
API: 05-103-07513  
Inspection: 700400133



39.96634, -108.9828, 5510.8ft, 254°  
02/21/2020 10:46:52 AM

Photo 3. Pit.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Banta Ridge 3  
API: 05-103-07513  
Inspection: 700400133



Photo 4. Separator & meter building.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Banta Ridge 3  
API: 05-103-07513  
Inspection: 700400133



**Photo 5. Stained soil next to tank.**

