

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/20/2020

Submitted Date:

02/20/2020

Document Number:

701000054

FIELD INSPECTION FORM

Loc ID 380605 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96340
Name of Operator: WIEPKING-FULLERTON ENERGY LLC
Address: 106 GLENMOOR LN
City: ENGLEWOOD State: CO Zip: 80113

Findings:

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Herian, Tim	(316) 655-9200	therian1@cox.net	all inspections
Shalberg, Greg	719-688-3547	gregshalberg@aol.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207704	WELL	PR	11/18/2006	OW	017-06639	WILDHORSE 4-1	PR

General Comment:

[Routine Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Elevated gravel road through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Wire fence around unit, wellhead and tanks		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Pump Jack	# 1		
Comment:	Lufkin 320		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	AJAX gas engine		
Corrective Action:			Date:
Type: Ancillary equipment	# 8		
Comment:	Gas scrubber, 2-chemical drums w/containment, day drum, 2-propane tanks, cathodic generator and rectifier		
Corrective Action:			Date:
Type: FWKO	# 1		
Comment:	FWKO on north side of tanks		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		38.946500,-103.007800

Comment: [South tank](#)

Corrective Action: _____ Date: _____

Paint

Condition: _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: [Shared berms](#)

Corrective Action: _____ Date: _____

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		38.946500,-103.007800

Comment: _____

Corrective Action: _____ Date: _____

Paint

Condition: _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: _____

Corrective Action: _____ Date: _____

Venting:

Yes/No	NO		
Comment:	_____		
Corrective Action:	_____		Date: _____

Flaring:

Type	_____		
Comment:	_____		
Corrective Action:	_____		Date: _____

Inspected Facilities

Facility ID: 207704 Type: WELL API Number: 017-06639 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT